Approved For Release 2002/06/11 : CIA-RDP66B00664R000100040045-7

7 19 4		d stiggt to the contract of t	Section Section 1
	1129Z 03 APR 63		
25X1A	DIRECTOR		
		Control of the second of the s	
1274	OPS (1-2-3-4-5-6)		
200	S/C (7)	ROUTINE	
i i		***	25X1A
	TOR: 1241Z 03 APR 63	de la caracteria de la	
25X1А Г	25X1A	Andrew Comments	71168
25X1A [•	0.42	8870
L	A. GRC-147		25X1A
	B. 355		
			17
	7 PL 15 29		
	ATDOTHA		
į	E. (1) CABIN PRESS FLUCTUATED 1500 FT IN AUT	O POSITION.	
	CORRECTIVE ACTION: REPLACE MAG. AMP.		
	(2) AUTO PILOT OSCILLATED SLIGHTLY IN PIT	CM.	9
	CORRECTIVE ACTION: PENDING INVESTIGA	Tran	
25X1A	(3) SHITTER POWER SWITCH FAILED		
	FILM EXP.	HELK APPROX	500
	CORRECTIVE ACTION: REPLACE SKUTTER PO		audi pr
16	· NEGATIVE	JWER SWITCH.	## ## ## ## ## ## ## ## ## ## ## ## ##
6,	» DC GEN		÷
Br	RUSH WEAR AND OPN NORMAL. MAX TEMP 90 DEGREES		E.
	MAA LEMP 90 DEGREES	S C.	

END OF MESSAGE

SECRET